

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

Form Approved
OMB No. 2040-0004

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

NAME: ATLANTA GOLD CORPORATION
ADDRESS: 2417 BANK DRIVE, SUITE 101
BOISE, ID 83705

FACILITY: ATLANTA GOLD PROJECT
LOCATION: 1.5 MILES SOUTH OF ATLANTA
ATLANTA, ID 83601

ATTN: WM. ERNEST SIMMONS, PRESIDENT

IDG910006	001-A
PERMIT NUMBER	DISCHARGE NUMBER

DMR Mailing ZIP CODE: 83705

MINOR


(SUBR 02)

DISCHARGE FROM 900 LEVEL ADIT TO MONT
External Outfall

MONITORING PERIOD			
MM/DD/YYYY		MM/DD/YYYY	
FROM	03/01/2015	TO	03/31/2015

No Discharge ☐

PARAMETER		QUANTITY OR LOADING			QUALITY OR CONCENTRATION				NO. EX	FREQUENCY OF ANALYSIS	SAMPLE TYPE
		VALUE	VALUE	UNITS	VALUE	VALUE	VALUE	UNITS			
Temperature, water deg. centigrade 00010 1 0 Effluent Gross	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	9.3	deg C		weekly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	19 DAILY MX	deg C		Weekly	GRAB
Temperature, water deg. centigrade 00010 5 0 Upstream Monitoring	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	4.8	deg C		monthly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	Req. Mon. DAILY MX	deg C		Monthly	GRAB
Temperature, water deg. centigrade 00010 6 0 Downstream Monitoring	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	4.5	deg C		monthly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	Req. Mon. DAILY MX	deg C		Monthly	GRAB
pH 00400 1 0 Effluent Gross	SAMPLE MEASUREMENT	*****	*****	*****	7.5	*****	7.7	SU		weekly	grab
	PERMIT REQUIREMENT	*****	*****	*****	6.5 INST MIN	*****	9 INST MAX	SU		Weekly	GRAB
Solids, total suspended 00530 1 0 Effluent Gross	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	7	mg/L		weekly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	30 DAILY MX	mg/L		Weekly	GRAB
Arsenic, total recoverable 00978 1 0 Effluent Gross	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	13	ug/L	1	weekly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	10 DAILY MX	ug/L		Weekly	GRAB
Arsenic, total recoverable 00978 5 0 Upstream Monitoring	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	23	ug/L		monthly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	Req. Mon. DAILY MX	ug/L		Monthly	GRAB

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER Wm. Ernest Simmons, President TYPED OR PRINTED	I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.	 SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	TELEPHONE	DATE
			208-424-3343	4-8-15
			AREA Code	NUMBER
				MM/DD/YYYY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) (see attached)
A MAXIMUM TEMPERATURE LIMIT OF 9 DEGREE C APPLIES TO THE DISCHARGE DURING PERIODS OF SALMONID SPAWNING

JCS
4/10/15

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

Form Approved
OMB No. 2040-0004

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

NAME: ATLANTA GOLD CORPORATION
ADDRESS: 2417 BANK DRIVE, SUITE 101
BOISE, ID 83705
FACILITY: ATLANTA GOLD PROJECT
LOCATION: 1.5 MILES SOUTH OF ATLANTA
ATLANTA, ID 83601
ATTN: WM. ERNEST SIMMONS, PRESIDENT

IDG910006
PERMIT NUMBER

001-A
DISCHARGE NUMBER

DMR Mailing ZIP CODE: 83705

MINOR

(SUBR 02)

DISCHARGE FROM 900 LEVEL ADIT TO MONT
External Outfall


MONITORING PERIOD

MM/DD/YYYY	TO	MM/DD/YYYY
03/01/2015		03/31/2015

APR 1 0 2015

No Discharge ☐

PARAMETER		QUANTITY OR LOADING			QUALITY OR CONCENTRATION				NO. EX	FREQUENCY OF ANALYSIS	SAMPLE TYPE
		VALUE	VALUE	UNITS	VALUE	VALUE	VALUE	UNITS			
Arsenic, total recoverable 00978 6 0 Downstream Monitoring	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	21	ug/L		monthly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	Req. Mon. DAILY MX	ug/L		Monthly	GRAB
Iron, total recoverable 00980 1 0 Effluent Gross	SAMPLE MEASUREMENT	*****	*****	*****	*****	*****	360	ug/L		weekly	grab
	PERMIT REQUIREMENT	*****	*****	*****	*****	*****	1000 DAILY MX	ug/L		Weekly	GRAB
Flow 74076 1 0 Effluent Gross	SAMPLE MEASUREMENT	46722	66456	gal/d	*****	*****	*****	*****		continuous	record
	PERMIT REQUIREMENT	Req. Mon. MO AVG	Req. Mon. DAILY MX	gal/d	*****	*****	*****	*****		Continuous	RECORD



NAME/TITLE PRINCIPAL EXECUTIVE OFFICER	I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.	TELEPHONE		DATE	
		AREA Code	NUMBER	MM/DD/YYYY	
Wm. Ernest Simmons, Pres			208-424-3343	4-8-15	
TYPED OR PRINTED					

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) (see attached)
A MAXIMUM TEMPERATURE LIMIT OF 9 DEGREE C APPLIES TO THE DISCHARGE DURING PERIODS OF SALMONID SPAWNING

NONCOMPLIANCE REPORT

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

January 2015 – During January, we had one effluent arsenic sample that was 13 ug/L. The other three samples (two prior and one after) were all at <5 ug/L.

March 2015 – The first effluent sample taken on March 2nd showed the effluent sample of 13 ug/L for arsenic. Although this is a little over the standards, it is still lower than the AG-26 baseline sampling site which was 23 ug/L on the same day.

The following week the effluent sample showed the arsenic had dropped down to 5 ug/L. After a little maintenance was done, the last three weekly effluent samples showed arsenic had dropped down to non-detectable at <5 ug/L.

